



HT-S23114

Details

Description: Genuine Hendrickson Air Spring - Double Convoluted

Alternate SKU: ABSP2B12RB-7897, 566.CT64683, 566.ER7897, 566.CT64602, 566.ER7897-45, SP2B12RB , 354-7897, 454-7897, 454-7897L, S-23114, C-23114, 2B9-495, AB-2B9-495, 64683, 64602, FD 200-23A 709, W01-358-7897, 002878, 2878, S2878, WA01-7897C

Weight (lb): 9

Specifications

Attribute	Value
Make	Hendrickson
Notes	(2) HT-S23114 air springs included in lift kit HT-UBL-001.
Bellows Color	Black
Bellows Material	Rubber
Air Spring Type	Double Convoluted

Cross Reference

Company	SKU
Dayton	354-7897, 454-7897, 454-7897L
Automann	ABSP2B12RB-7897, 566.CT64683, 566.ER7897, 566.CT64602, 566.ER7897-45
Flagg/Triangle	AS-4709
Goodyear	2B9-495
Firestone	W01-358-7897

© 2026 The Universal Group

Continental	64683
Goodyear Bellows	578-92-3-217
Firestone Bellows	20-1
Automann Bellows	SP2B12RB
Continental Bellows	FD 200-23
Flagg/Triangle Bellows	FD 200-23

Related Products



HT-UBL-001

Description: GENUINE HENDRICKSON INTRAAX AAT/HT230/300 UNDER BEAM LIFT Kit

Alternate SKU: 334-2013, 3342013, AB1DKM58-8109, AB1DKM588109, UBL-001, UBL001, H-UBL-001, HUBL001, HTUBL001

Weight (lb): 70

© 2026 The Universal Group