


AB-2B12-309

Details

Description: Genuine Goodyear Air Spring - Double Convoluted

Alternate SKU: 2B12-309, 578-92-3-309, 354-7400, 454-7400, 454-7400L, W01-358-7400, 7400, 1003587400C, 566.ER7400, 566.CT64270, ABSP2B22R-7400, 693230, FD 330-22 313, 64270, 16-10769-000, 04-0080, 4-0080, S-1013, 90557016, 90557018, 1027519, AS74000, AS7400, AS-4313, V SP 2 B 22 R-7400, 2726, 554788C1, 670199, 3130488, AS-0003, M3506, AS214-7400, SC2020, PMABG-7400

Weight (lb): 15

Specifications

Attribute	Value
Make	Freightliner, Navistar/International
Top Plate Bolt Hole Quantity	3
Bottom Plate Bolt Hole Quantity	2
Top Plate Diameter	9 in
Bottom Plate Diameter	9 in
Minimum Height	4.2 in
Maximum Height	10.9 in
Top Plate Center To Center Diameter	6.2 in
Bottom Plate Center To Center Diameter	6.2 in
Bottom Plate Alignment	Parallel
Bracket	No
Bumper	Yes
Bellows Number	578-92-3-309
Bellows Color	Black
Bellows Material	Textile Reinforced Polymer Rubber
Air Spring Type	Double Convoluted

Cross Reference

Company	SKU
Dayton	354-7400, 454-7400, 454-7400L
Automann	566.ER7400, 566.CT64270, ABSP2B22R-7400
Flagg/Triangle	AS-4313
Goodyear	2B12-309
Firestone	W01-358-7400
Continental	64270
Goodyear Bellows	578-92-3-309
Firestone Bellows	22, 22C
Continental Bellows	FD 330-22
Flagg/Triangle Bellows	6316
Automann Bellows	SP2B22R
Watson & Chalin	AS-0003
Ridewell	1003587400C, S-788-C
Neway	905-57-016, TC-144-4
Freightliner	16-10769-000
GMC	693230
Reyco	2726
Hendrickson	C-1013
Navistar/International	554788C1