

SSA-83209

Details

Description: Genuine Gabriel Fleetline 83000 Shock Absorber

Alternate SKU: M66710, A83209, 83209, S-4089, S4089, A-4089, A4089, 6710, 6894, 34768, 66672, 66710, 557015, SSA83209

Weight (lb): 8



Specifications

Attribute	Value
Make	Advance Mixer, Chevrolet, Ford, GMC, Mack, Navistar/International, Neway, Reyco, Trailmobile, Western Star
Upper Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Lower Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Compressed Length	17.61 in
Extended Length	29.64 in
Shock Stroke	12.03 in
Length Measuring Points	Bushing center to bushing center
Gas Charged	No
Adjustable Damping	No
Bore Size	1.375 in
Upper Mount Bushing Inside Diameter	0.75 in
Lower Mount Bushing Inside	0.75 in

Diameter	
Cylinder Diameter	2 in
Dust Shield Included	Yes
Type	Telescopic

Cross Reference

Company	SKU
ACDelco	508-68
Advance Mixer	14626 ADV
Arvin	665044, 727609
Automann	A83209
Batco	1083209
Bulldog	HD1214-0580, HD1215-0093
Chevrolet	684280, 4940600, 35901-0001
Damon	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205, ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766
Dayton	441-83209, M66710
Euclid	E83205, E83209
FCS	F347243
Flagg/Triangle	F66710
Fleetrite	AMS600108, AMS600142, AMS660108, AMS660142, AMS85768
Fleetwood	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205, ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766
Forest River	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205, ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766
Gabriel	83209
GMC	684280, 4940600, 35901-0001
Gold	9160933
Hendrickson	A-4089, S-4089
Itasca	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205, ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766
Kenworth	680279, 90044025PLUS
Koni	8805-1018, 88-1457-SP1, 88-1468, 88-5162
Mack	651151, 25625187, 25632561, 14QK-2100P2, 14QK-2105, 14QK-2107, 14QK-366P4, 14QK-372M2, 5966-90044025
Meritor	M83209
Monaco	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205,

	ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766
Monroe	6710, 6894, 16770, 34768, 66672, 66710, 557001, 557015
Motor Coach	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205, ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766
Motorcraft	ASH-1022, ASH-1205, ASH-1228, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766, CAT-768, CAX-710, CAX-894
Navistar/International	90044025, 790335C91
Neway	90044025, 90044682, AR-1654
Oshkosh	1139069 MTM
Peterbilt	680279, 90044025PLUS
Reyco	17146-01
Sachs	315432, 317776
Thor	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205, ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766
Trailmobile	43-8-002
Truckmaster	680279
Volvo	1091351, 3919585, 3919914, 83176208, 35901-0001, SA3209
Western Star	90044025, 35901-0001
Winnebago	1C34-18045-AA, 1C34-18045-JA, 9U94-18045-AA, 9U9Z-18124-A, ASH-1022, ASH-1205, ASH-1228, ASH-1229, ASH-25822, ASH-25823, ASH-294, AT-620, AT-766