



H-50898-002

Details

Description: GENUINE HENDRICKSON AIR SPRING ASSEMBLY

Alternate SKU: 1R12-402, 566243097, 452-9297L, 452-9297, 352-117, 352-9297, AB1DK23M-9297, 566.CT66978, 566.ER9297, 050898-002L, 50898-002L, 050898-002, 050898-2, 50898-002, 50898-2, 050898-001, 050898-1, 50898-001, 50898-1, 9297, 064651-002, 64651-002, 064651-2, 64651-2, H50898002, H50898001, 1DK23M-9297X, 1DK23P9297, W01-358-9297, 9297, AS99110, AS9297, 50898-002, 50898-001, 50898-2, 50898-1, AB-1R12-402, H-50898-001, 050898-002, 050898-001, 9 10-18.5 P 935 (BK), 9 10-18.5 P 935, 66978, AS-8451, AS-8520, AS-8935

Weight (lb): 16



Specifications

Attribute	Value
Make	Ford, Hendrickson
Notes	Equivalent to Goodyear AB-1R12-402
Top Plate Bolt Hole Quantity	2
Bottom Plate Bolt Hole Quantity	1
Top Plate Diameter	9 in
Bottom Plate Diameter	10 in
Minimum Height	8.1 in
Maximum Height	22 in
Bellows Color	Black
Bellows Material	Rubber
Air Spring Type	Rolling Lobe

Cross Reference

Company	SKU
Automann	AB1DK23M-9297, 566.CT66978, 566.ER9297
Continental	66978
Dayton	50898-002L, 352-117, 352-2927
Firestone	W01-358-9297
Flagg/Triangle	AS-8451, AS-8520, AS-8935
Goodyear	1R12-402
Hendrickson	050898-002
Automann Bellows	1T15M-8
Flagg/Triangle Bellows	6363/91
Goodyear Bellows	566-24-1-012, 566-24-3-097
Firestone Bellows	1T15M8
Continental Bellows	9 10-18.5