



H-50899-002

Details

Description: GENUINE HENDRICKSON AIR SPRING ASSEMBLY (1R12-404)

Alternate SKU: 50899-002L, 50899002L, 352-9375, 3529375, AB1DK23M-9375, 566.CT68616, 566.ER9375, 050899-002, 50899-002, 050899002, 50899002, 050899-001, 50899-001, 050899001, 50899001, 1R12-404, 1R12404, 1S12-031, 1S12031, AS-8451, AS8451, AS9375, 9375, 364QS27, 57QL414M, H50899002, 1DK23P9375, FS9375, 50899-2, 50899-1, SC2773, 9 10-18.5 P 451 (BK)

Weight (lb): 19

Specifications

Attribute	Value
Make	Hendrickson
Top Plate Bolt Hole Quantity	2
Bottom Plate Bolt Hole Quantity	1
Top Plate Diameter	9 in
Bottom Plate Diameter	10 in
Minimum Height	8.1 in
Maximum Height	22 in
Bellows Color	Black
Bellows Material	Rubber
Air Spring Type	Rolling Lobe

Cross Reference

Company	SKU
Automann	AB1DK23M-9375, 566.CT68616, 566.ER9375
Continental	68616
Dayton	50899-002L, 352-9375
Firestone	W01-358-9375
Flagg/Triangle	AS-8451
Goodyear	1R12-404
Hendrickson	050899-002
Meritor	FS9375
Automann Bellows	1DK23M
Flagg/Triangle Bellows	6391, 6363
Goodyear Bellows	566-24-1-012, 566-24-3-097, 566-24-3-111
Firestone Bellows	1T15M-8, 1T15M8
Continental Bellows	9 10-18.5