



ABC-1S5-175

Details

Description: Genuine Goodyear Air Spring - Sleeve/Cabin
Alternate SKU: 1S5-175, 579101116, 453-7215L, 453-7215, ABSZ70-7215, ABSZ70-7207, ABSZ70-7205, 569.CT67638, 569.CT68161, ABSZ70-7215, W02-358-7215, W02-358-7205, W02-358-7207, WA02-7207C, W02-358-7215, ABSZ70-7111, 7215, 7205, 7207, 7111, SC31-B207, SC31-Y215, 68161, SC31-Y205, 67638, AS7205, AS7215, AS-5205, AS-5215, AS72050, AS72150, 66003-3406, 18-40977-000, 18-52651-000, 18-66715-000, 18-73178-000, 660033406, ABC-7215

Weight (lb): 1

Specifications

Attribute	Value
Make	Freightliner, Volvo, Western Star
Top Plate Bolt Hole Quantity	1
Bottom Plate Bolt Hole Quantity	1
Top Plate Diameter	2.93 in
Bottom Plate Diameter	2.89 in
Material	Rubber
Bumper	Yes
Bellows Number	579-10-1-083
Air Spring Type	Sleeve

Cross Reference

Company	SKU
---------	-----

Dayton	453-7215L, 353-7215
Automann	ABSZ70-7215
Flagg/Triangle	AS-5215
Goodyear	1S5-175
Firestone	W02-358-7215, W02-358-7205, W02-358-7207
Continental	68161, 67638
Meritor	E-FS7215