



HT-S42482-1

Details

Description: Genuine Hendrickson MAXX22T Air Disc Brake Pad Service Kit (1-axle)

Alternate SKU: S-42482-1, S-42229-1, S-41281-1, S-41167-1, S-35303-1, HT-S-42482-1, HT-S42229-1, HT-S41281-1, HT-S41167-1, HT-S35303-1, GTD1777H, 640-222-938-2, 141.D1777FS-HM, 141.D1777SD-HM, 141.D1777WHXD26N, 141.D1777WHXD26N, 141.D1777WHSD23N, 141.D1777WHFS20N, 141.13D1777WHFS20N

Weight (lb): 22

Specifications

Attribute	Value
Make	Freightliner, Hendrickson, Kenworth, Mack, Navistar/International, Peterbilt, Volvo
Notes	Includes (4) pads, (2) springs, (2) holder brackets, (2) screws and (2) plugs. Replaces: HT-S42229-1, HT-S41281-1, HT-S41167-1, HT-S35303-1.

Cross Reference

Company	SKU
Dayton	640-222-927-2, 640-222-938-2
Automann	141.D1777WHXD26N, 141.D1777WHSD23N, 141.D1777WHFS20N, 141.13D1777WHFS20N
Hendrickson	S-42482-1