


Hendrickson MAXAIR / AL405 Air Suspension



For more information visit www.theuniversalgroup.com or call 1.800.225.1845

Universal Group®




The Universal Group, LLC
1025 Thomas Busch Memorial Highway
Pennsauken, New Jersey 08110
1.800.225.1845
856.488.1800
Fax 1.800.360.9636

POWER10®
PARTS
Customer Driven, Quality Directed

© 2018 The Universal Group, LLC All Rights Reserved

Hendrickson

MAXAIR / AL405 Air Suspension
Mack "Twisted Sister"
Tandem Axle Air Suspension



50-433-OE	50-435-OE	H-22186-000	H-49947-000
LH Main Support Member (H-58691-000)	RH Main Support Member (H-58768-000)	Torque Rod Frame Bracket (Flagg E336-50, Dayton Parts 338-	Spherical Washer (Flagg HS123, Dayton Parts 334-1695)
			

H-57241-006	H-58648-000	HT-58701-001 HT-58702-001	H-58772-001
Shock Absorber (Flagg HS107, Dayton Parts 341-	QUIK-ALIGN Pivot Bushing (Flagg HS102, Dayton Parts 321-387)	LH Lower Shock Bracket RH Lower Shock Bracket (Dayton Parts 338-1926, 338-1927)	Frame Hanger (Dayton Parts 338-1924)
			

H-58776-000	H-59580-006 H-64237-003 H-59582-005 H-59582-006 H-59582-008	Spring Seat Front (4.5°) Spring Seat Front (7.5°) Spring Seat Front (12.0°) Spring Seat Front (12.5°) Spring Seat Front (13.5°)
U-Bolt Spacer Tuber 		

H-58786-002	H-60661-000	H-60662-000
Air Spring Assembly 	QUIK-ALIGN Concentric Base (in kit H-60683-001) (Flagg HS125, Dayton Parts 334-1694)	QUIK ALIGN Eccentric Base (in kit H-60683-001) (Flagg HS126, Dayton Parts 334-1693)
		

Kit 60683-001	H-65084-000
Kit Contains 6 pcs. H-60661-000 2 pcs. H-60662-000 4 pcs. H-58705-003 4 pcs. H-60266-000 8 pcs. H-22962-034 4 pcs. H-58648-000  Service Kit, QUIK ALIGN w/bushing (Dayton Parts 334-1690)	Top Pad  (Dayton Parts 338-1925)

Universal Group®



www.theuniversalgroup.com