

SSA-83122

Details

Description: Genuine Gabriel Fleetline 83000 Shock Absorber

Alternate SKU: M65412, A83122, 83122, 47902-8, 479028, 47902-13, 4790213, 6994, 65412, 65479, 551002, SSA83122

Weight (lb): 6



Specifications

Attribute	Value
Make	Autocar, Chevrolet, Ford, Fruehauf, GMC, Hendrickson, Isuzu, Neway, Oshkosh, Volvo, Western Star
Upper Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Lower Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Compressed Length	15.79 in
Extended Length	25.28 in
Shock Stroke	9.49 in
Length Measuring Points	Bushing center to bushing center
Gas Charged	No
Adjustable Damping	No
Bore Size	1.375 in
Upper Mount Bushing Inside Diameter	0.75 in
Lower Mount Bushing Inside	0.75 in

Diameter	
Cylinder Diameter	2 in
Dust Shield Included	Yes
Type	Telescopic

Cross Reference

Company	SKU
Autocar	727602
Automann	A83122
Bulldog	HD1215-0110, HD1215-0133
Chevrolet	12474915, 15963161
Damon	9U94-18080-AA, 9U9Z-18125-A, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621
Dayton	441-83122, M65412, M66897
Euclid	E83218
FCS	F347309
Flagg/Triangle	F66833, F65412, F65479
Fleetrite	AMS650412, AMS650479
Fleetwood	9U94-18080-AA, 9U9Z-18125-A, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621
Forest River	9U94-18080-AA, 9U9Z-18125-A, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621
Freightliner	47902-13
Fruehauf	5116-117, UCE-9399-1
Gabriel	83122, 89406
Gillig	90044683, 82-01878
GMC	12474915, 15963161
Gold	9180196
Great Dane	18164-01
Hendrickson	47902-13, 47902-8, 60675-007
Isuzu	12474915
Itasca	9U94-18080-AA, 9U9Z-18125-A, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621
Kenworth	665784, 47902-13PLUS
Koni	8805-1019, 88-1458-SP1, 88-1458-SP2, 88-5163
KYB	KG6008A
Mack	14QK-372M3
Marmon	576451, 37-1-1

Meritor	M83122
Monaco	9U94-18080-AA, 9U9Z-18125-A, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621
Monroe	6025, 6994, 16772, 16776, 65412, 65479, 66833, 551002, 557007
Motor Coach	9U94-18080-AA, 9U9Z-18125-A, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621
Motorcraft	ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621, AX-97A
Neway	6025, 90044679, 90044683, 90044688
Oshkosh	665060, 26228-A, 6HS773 MTM, 7HS237 MTM
Peterbilt	665784, 47902-13PLUS, 47902-13PLUS-2
Reyco	17403-01, 18164-01
Sachs	315542, 317774, 410058
Thor	9U94-18080-AA, 9U9Z-18125-A, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, AT-621
Truckmaster	665784
Volvo	1091348, 3199957, 3919957
Western Star	35066-4413, 47902-13, 47902-8
Winnebago	9U94-18080-AA, 9U9Z-18125-A, 9U9Z-18125-B, ASH-1023, ASH-1206, ASH-1230, ASH-137, ASH-25824, ASH-25825 , AT-621, HU9Z-18125-B