

SSA-83123

Details

Description: Genuine Gabriel Fleetline 83000 Shock Absorber

Alternate SKU: M65481, A83123, 83123, 659004, 654898, 654894, 60670-008L, 60670008L, 60670-008, 60670008, 60670-004, 60670004, 60670-001, 60670001, 060670-008L, 060670008L, 060670008L, 060670-008, 060670008, 060670-004, 060670004, 060670-001, 060670001, 47902-9, 479029, 479029, 47902-27, 4790227, 47902-19, 4790219, 66613, 66638, 66661, 66671, 557020, SSA83123, M66613

Weight (lb): 6



Specifications

Attribute	Value
Make	Ford, Hendrickson, Kenworth, Mack, Navistar/International, Neway, Peterbilt, Reyco, Watson & Chalin
Upper Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Lower Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Compressed Length	16.41 in
Extended Length	26.65 in
Shock Stroke	10.24 in
Length Measuring Points	Bushing center to bushing center
Gas Charged	No
Adjustable Damping	No
Bore Size	1.375 in
Upper Mount Bushing Inside Diameter	0.75 in
Lower Mount Bushing Inside	0.75 in

Diameter	
Cylinder Diameter	2 in
Dust Shield Included	Yes
Type	Telescopic

Cross Reference

Company	SKU
ACDelco	508-57
Automann	A83123
Bulldog	HD1214-0530, HD1214-0566, HD1215-0059
Dayton	441-83123, M65481, M66613, M66638
FCS	F347248
Flagg/Triangle	F66638
Fleetrite	AMS600125, AMS650481, AMS660125, AMS660216
Gabriel	83123, 89405
Gillig	90044046
Gold	8160909
Hendrickson	654894, 654898, 659004, 47902-19, 47902-27, 47902-9, 60670-001, 60670-004, 60670-008, 60670-008L, 60675-013
Kenworth	665783, 47902-19, 60670-004, 60670-008, 60670-008L, 60670-008PLUS, 60670-008PLUS-2
KYB	KG6416
Mack	14QK-375M, 14QK-393AM, 47902-9
Marmon	51-163-7
Meritor	M83123
Monroe	6613, 6916, 16780, 66613, 66638, 65481, 66661, 66671, 557020
Motorcraft	CAX-916
Navistar/International	537524C91, 537525C91
Neway	90044046, AR-2598
Oshkosh	6HA961 MTM
Peterbilt	665783, 60670-008, 60670-008L, 60670-008PLUS, 60670-008PLUS-2
Reyco	19623-01
Sachs	317934
Truckmaster	665783
Volvo	1091359, 3919573, 3919921, 83176199, 35901-0011, SA3123
Watson & Chalin	11724

