



SSA-83147

Details

Description: Genuine Gabriel Fleetline 83000 Shock Absorber

Alternate SKU: M65505, 65505, A83147, 83147, 98583-016, 98583016, 659155, 654896, 565.ER3054, SSA83147, 060670-006, 60670-006L, 060670-006V, 60670-006, 60670-006L, 60670-006V, 341-60670-6, A83147, 14QK-424M, 14QK424M, 20570098, 1367383, 1367383MTM, 98583-016, 098583-016, F347218, SSA-83147, 83147, ABPN32G900069, 65505, AMS65505, M83147, 925055, 8160906, H-60670-006

Weight (lb): 6

Specifications

Attribute	Value
Make	Hendrickson, Mack, Oshkosh, Thomas
Upper Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Lower Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Compressed Length	17.4 in
Extended Length	28.54 in
Shock Stroke	11.15 in
Length Measuring Points	Bushing center to bushing center
Gas Charged	No
Adjustable Damping	No
Bore Size	1.375 in
Upper Mount Bushing Inside Diameter	20 mm
Lower Mount Bushing Inside Diameter	20 mm

Cylinder Diameter	2 in
Dust Shield Included	Yes
Type	Telescopic

Cross Reference

Company	SKU
Alliance Truck Parts	ABP N32 G900069, ABP N32 O900069
Automann	A83147
Dayton	341-60670-6, M65505
FCS	F347218
Gabriel	83147
Gold	8160906
Hendrickson	654896, 659155, 60670-006, 60670-006L, 60670-006V, 98583-016
Mack	20570098, 14QK-424M
Meritor	M83147
Monroe	65505
Oshkosh	1367383 MTM
Thomas	60670-006
TRP Parts	HS 83147