



SSA-85061

Details

Description: Genuine Gabriel Fleetline 85000 Shock Absorber

Alternate SKU: M65494, A85061, 85061, 65130, 65494, SSA-85098, SSA85098, 85098, SSA85061

Weight (lb): 8

Specifications

Attribute	Value
Make	Mack, Volvo
Notes	SSA-85061 replaces SSA-85098.
Upper Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Lower Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Compressed Length	15.25 in
Extended Length	24.76 in
Shock Stroke	9.51 in
Length Measuring Points	Bushing center to bushing center
Gas Charged	No
Adjustable Damping	No
Bore Size	1.625 in
Upper Mount Bushing Inside Diameter	16 mm

Lower Mount Bushing Inside Diameter	16 mm
Cylinder Diameter	2.19 in
Dust Shield Included	Yes
Type	Telescopic

Cross Reference

Company	SKU
Alliance Truck Parts	ABP N32 G900040, ABP N32 G900080, ABP N32 O900040, ABP N32 O900080
Automann	A85061
Bulldog	HD1215-0074
Chalmers	K880247
Dayton	441-85061, M65494
FCS	F347205, F347207
Flagg/Triangle	F65494
Fleetrite	AMS650130
Gabriel	85061, 89450, 89502
Gold	8160112, 9180140
Mack	20513881, 20897198, 20973993, 21436096, 23292027, 23292028, 141700000373, 141700000380, 141700005839, 471700002626, 14QK-2136M, 14QK-3107M, 14QK-3114M, 14QK-431M, SDA141700000380
Marathon	58119-MB
Meritor	M85061
Monroe	65130, 65494
Powerhouse Products	20433424, 20973993, 21436086, 141700005838
Renegade	20433424, 20973993, 21436086, 141700005838
Sachs	315606, 315607, 315608, 316313, 410036, 141700000373, 141700000380, 141700002626, 141700005838, 141700005839, 471700014316
TRP Parts	HS 85061, HS 85098
Volvo	3092842, 3949241, 8071881, 8078195, 20433424, 20513881, 20973993, 21436086, 23288402, 23288403, 83176223, 85134402, 41700014316, 141700000373, 141700005838, 471700014316, RC SA5061, SA5061