



H-64179-004

Details

Description: Genuine Hendrickson Auxiliary Load Spring Service Kit (one side)

Alternate SKU: 334-1720, 3341720, MHS225K, 064179-004, 64179-004, 064179004, 64179004, H64179004, HS99, E14534

Weight (lb): 4

Specifications

Attribute	Value
Make	Hendrickson

Cross Reference

Company	SKU
Automann	MHS225K
Dayton	334-1720
Flagg/Triangle	HS99
Hendrickson	064179-004
Meritor	E14534