



H-69116-002

Details

Description: Genuine Hendrickson AIRTEK Air Spring - Rolling Lobe

Alternate SKU: 69116-002L, 069116-002L, 069116-002, 69116-002, 069116002, 69116002, AB1DK10A-9911, 69116-2, 566.CT69914, 569.CT69914, H69116002, 69914, 453-9911, 353-9911, 59823-2C, 069782-002, 69782-002, 69782-2, 067874-002, 67874-002, 67874-2, AS-8325, AS99110, AS9911, 6 6.5B-11 P 235

Weight (lb): 4



Specifications

Attribute	Value
Make	Freightliner, Hendrickson, Sterling, Western Star
Notes	Freightliner, Western Star, Sterling - After 2010
Top Plate Bolt Hole Quantity	2
Bottom Plate Bolt Hole Quantity	1
Top Plate Diameter	6.31 in
Bottom Plate Diameter	6.5 in
Minimum Height	5.9 in
Maximum Height	14.7 in
Bellows Color	Black
Bellows Material	Rubber
Air Spring Type	Rolling Lobe

Cross Reference

Company	SKU
Automann	AB1DK10A-9911, 566.CT69914, 569.CT69914
Continental	69914
Dayton	69116-002L, 453-9911, 353-9911
Firestone	W26-358-9911
Hendrickson	69116-002
Continental Bellows	6 6.5B-11
Flagg/Triangle	AS-8325
Flagg/Triangle Bellows	1DK23K, 1T15M6, 566-24-1-008, 6363, 91016