



HT-S28890

Details

Description: Genuine Hendrickson INTRAAX Cam Tube Service Kit for 16.5in Brake

Alternate SKU: 03-1452, 3-1452, 031452, 31452, 110.2505, 1102505, S-28890, S28890, 31451, HTS28890, 03-1451, 3-1451, 031451, E11897H

Weight (lb): 3

Specifications

Attribute	Value
Make	Hendrickson

Cross Reference

Company	SKU
Automann	110.2505
Dayton	03-1452
Hendrickson	S-28890
Meritor	E11897H