

SSA-85702

Details

Description: Genuine Gabriel Fleetline 85000 Shock Absorber

Alternate SKU: M74408, A85702, 85702, 65449, 65477, 74408, SSA85702

Weight (lb): 9



Specifications

Attribute	Value
Make	Mack, Reyco
Upper Mount Type	Eye Ring Bushing
Lower Mount Type	Eye Ring Bushing
Compressed Length	15.85 in
Extended Length	23.76 in
Shock Stroke	7.91 in
Length Measuring Points	Bushing center to bushing center
Gas Charged	No
Adjustable Damping	No
Bore Size	1.625 in
Upper Mount Bushing Inside Diameter	1 in
Lower Mount Bushing Inside Diameter	1 in

Cylinder Diameter	2.75 in
Dust Shield Included	Yes
Type	Telescopic

Cross Reference

Company	SKU
ACDelco	507-16
Arvin	680331
Automann	A85702
Bulldog	HD1116-0046
Chevrolet	4975516, 4975550, 22012082, 22045526, 22046481, 22052014, 507-16, 97-2210-00156
Dayton	M74408
Euclid	E85702
Fleetrite	AMS650449, AMS700403
Gabriel	85702
GMC	4975516, 4975550, 22012082, 22045526, 22046481, 22052014, 507-16, 97-2210-00156
Koni	90-2434
Mack	1252607B000
Mohawk	22012082
Monroe	65449, 65477, 74408
Motor Coach	22045526, 22052014, G1011822, G1201339, OE10086S
Muncie Transit Supply	MR25767, MR2960
Nova Bus	22045526, 22052014, 10086S, G1011822, G1201339, G1203223
Prevost	19502711, 0822045526, G1011822
Reyco	16230-01
Ridewell	680101, 1252607B000, S2607B
Spartan	S2607B
TMC	680349, 22045526, 22052014, G1011822
Volvo	3199979, 3919965, 3919978, 3919979, 3919980, 19502711