



SSA-85978

Details

Description: Genuine Gabriel FleetLine 85000 Series Shock Absorber

Alternate SKU: 441-85978, HD1215-0083, 65483, H-60675-001, H-60675-009, 060675-009, 60675-009, 60675009, 60675-001, 60675001, M65483, 341-60675-1, 341606751, 341-60675-9, 341606759, A85978, 85978, SSA-85978, SSA85978, 44185978, HD12150083, H60675001, H60675009, 060675009

Weight (lb): 8

Specifications

Attribute	Value
Make	Ford, Hendrickson, Mack, Volvo
Upper Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Lower Mount Type	Eye Ring Bushing Steel Sleeve - Centered
Compressed Length	18.16 in
Extended Length	29.84 in
Shock Stroke	11.69 in
Length Measuring Points	Bushing center to bushing center
Gas Charged	No
Adjustable Damping	No
Bore Size	1.625 in
Upper Mount Bushing Inside Diameter	0.79 in
Lower Mount Bushing Inside Diameter	0.79 in

Cylinder Diameter	2.38 in
Dust Shield Included	Yes
Type	Telescopic

Cross Reference

Company	SKU
Automann	A85978
Bulldog	HD1215-0083
Dayton	441-85978, M65483, HD1215-0083
FCS	F347235
Gabriel	85978
Gold	5000856
Hendrickson	58623-1, 60665-008, 60675-001, 60675-001L, 60675-009, 60675-014
Mack	8083872, 23818296, 14QK-423M, 60675-001, 60675-001L
Monroe	65483
Sachs	316822
Volvo	8083872, 60675-001, 60675-001L