




AB-2B9-201

Details

Description: Genuine Goodyear Air Spring - Double Convoluted

Alternate SKU: 2B9-201, AS-4310, AS-4499, 4310, 4499, E-FS6902, AS6902, AB2B9201, 6902, SP2B12R6902, S-2630, B-2630, 4848, AS0002, 57006902, 554784C1, 566.CT6450902, 566.CT64515, 566.ER6902, 566.ER6935, ABSP2B12R-6902, ABSP2B12R-6935, FD 200-19 499, 64515, 354-6902, 354-6935, 454-6902, 454-6935, W01-358-6902, W01-358-6935, W01-358-6911, 16-14318-000, 2B9-201, R-B-14318, S-14318, S-2630, 554784C1, AS-4310, AS-0002, 2B9-493, 55478C1

Weight (lb): 9



Specifications

Attribute	Value
Make	Freightliner, Hendrickson, Meritor, Navistar/International, Reyco, Watson & Chalin
Top Plate Bolt Hole Quantity	3
Bottom Plate Bolt Hole Quantity	2
Top Plate Diameter	6.4 in
Bottom Plate Diameter	6.4 in
Minimum Height	3.8 in
Maximum Height	10.8 in
Top Plate Center To Center Diameter	3.5 in
Bottom Plate Center To Center Diameter	3.5 in
Bottom Plate Alignment	Parallel
Bracket	No

Bumper	Yes
Bellows Number	578-92-3-202
Bellows Color	Black
Bellows Material	Textile Reinforced Polymer Rubber
Air Spring Type	Double Convolute

Cross Reference

Company	SKU
Automann	566.CT6450902, 566.CT64515, 566.ER6902, 566.ER6935, ABSP2B12R-6902, ABSP2B12R-6935
Continental	64515
Dayton	454-6935, 354-6935, 454-6902, 354-6902
Firestone	W01-358-6902, W01-358-6935, W01-358-6911
Flagg/Triangle	AS-4310
Goodyear	2B9-201
Automann Bellows	SP2B12R
Flagg/Triangle Bellows	6325
Goodyear Bellows	578-92-3-202
Firestone Bellows	20F, 20
Continental Bellows	FD 200-19