



HT-RB14318

Details

Description: Genuine Hendrickson Lift Air Spring - Double Convoluted (S-14318)

Alternate SKU: R-B-14318, S-14318, W01-358-6935, W01-358-6902, 64515, 454-6935, 354-6935, 454-6902, 354-6902, B-14318, 566.CT64509, 566.ER6935, ABSP2B12R-6902, 566.CT64515, ABSP2B12R-6935, 566.ER6902, AS-4310, FD 200-19 499, 2B9-201, 2B9-239, AS-0002, 16-14318-000, 554784C1, 201548, AB-6902, RB14318, B14318, W013586935, 6935, FD20019499, AB-2B9-201, AB-2B9-239, AB6902, AS4310, AS-4499

Weight (lb): 8

Specifications

Attribute	Value
Make	Hendrickson
Notes	Used with HT-RB14249

Cross Reference

Company	SKU
Dayton	454-6935, 354-6935, 454-6902, 354-6902, B-14318
Automann	566.CT64509, 566.ER6935, ABSP2B12R-6902, 566.CT64515, ABSP2B12R-6935, 566.ER6902
Flagg/Triangle	AS-4310
Goodyear	2B9-201, 2B9-239
Firestone	W01-358-6935
Meritor	201548
Continental	64515
Goodyear Bellows	578-92-3-202

Firestone Bellows	20F
Continental Bellows	FD 200-19
Flagg/Triangle Bellows	6325
Automann Bellows	SP2B12R