



HT-S42229-1

Details

Description: Genuine Hendrickson MAXX22T Air Disc Brake Pad Service Kit (1-axle)

Alternate SKU: S-42229-1, S-41167-1, S-35303-1, GTD1777H, 640-222-938-2, 141.D1777FS-HM, 141.D1777SD-HM, 141.D1777WHXD26N, 141.D1777WHXD26N, 141.D1777WHSD23N, 141.D1777WHFS20N, HT-S41167-1

Weight (lb): 22

Specifications

Attribute	Value
Make	Hendrickson
Notes	Includes (4) pads, (2) springs, (2) holder brackets, (2) screws and (2) plugs. Use with calipers HT-S35973-L & HT-S35973-R. Replaces S-41167-1, S-35303-1.

Cross Reference

Company	SKU
Dayton	640-222-927-2, 640-222-938-2
Automann	141.D1777WHXD26N, 141.D1777WHSD23N, 141.D1777WHFS20N